

EXHIBIT G

APPENDIX C

Photograph Log and Photographs

PHOTO LOG

The photographs were taken using a PENTAX Optio W80 digital camera during the inspection. Ashley Toy took all photographs. Original copies of the Photos are on a CD in the file. Photo coordinates were recorded using a GPS unit.

Photo Reference	Photo Filename ¹	Coordinates Where Photo Taken	Description
Photo 1	2011-06-17--09.12.08.JPG	N 39.1584370667 ,W - 78.9364804667	GPS unit showing time of 9:12:08 AM.
Photo 2	2011-06-17--09.39.59.JPG	N 39.1582043333 ,W - 78.9365443333	Biosecurity warning sign at entrance to the Facility.
Photo 3	2011-06-17--09.40.13.JPG	N 39.1582016 ,W -78.9365518	Lane sign at entrance to the Facility with the Pilgrim's Pride logo and the name "Tony & Lois Alt."
Photo 4	2011-06-17--09.42.04.JPG	N 39.157647 ,W -78.936499	From the north end of House 1, view of the west side of House 1. Slope is away from house but inclines to the tree line. Area is predominately vegetated. Side vents and exhaust fans for the tunnel ventilation system are seen. PVC pipes low on the house are for rodent control.
Photo 5	2011-06-17--09.42.51.JPG	N 39.1576419333 ,W - 78.9365140667	North end of House 1. House 1 has sliding door with concrete pad. Concrete pad is width of the door (approx. 15') and extends from house (approx. 8').
Photo 6	2011-06-17--09.45.20.JPG	N 39.1575592667 ,W - 78.9363926	View between House 1 (right) and House 2 (left). Feed bins in foreground with propane tanks behind feed bins. Area is predominately grassed.
Photo 7	2011-06-17--09.48.30.JPG	N 39.1574588667 ,W - 78.9361014	View between House 2 (right) and House 3 (left). No feed bins or propane tanks. Area is vegetated with high grasses. Side vents are seen.
Photo 8	2011-06-17--09.49.39.JPG	N 39.1572646667 ,W - 78.935787	View between House 3 (right) and House 4 (left). Feed bins in foreground with propane tanks behind feed bins. Area is predominately grassed.

¹ Filename based on date and time photo was taken where time is expressed based on the 24 hour clock. Format is YYYY-MM-DD--HH-MM-SS.JPG.

Photo Reference	Photo Filename ¹	Coordinates Where Photo Taken	Description
Photo 9	2011-06-17--09.51.37.JPG	N 39.1571116 ,W -78.935456	View between House 4 (right) and House 5 (left). No feed bins or propane tanks. Area is vegetated with high grasses. Side vents are seen.
Photo 10	2011-06-17--09.52.31.JPG	N 39.1569738 ,W -78.9351196	View between House 5 (right) and House 6 (left). Feed bins in foreground with propane tanks behind feed bins. Area is predominately grassed with shorter grass in the middle.
Photo 11	2011-06-17--09.53.15.JPG	N 39.1568386667 ,W -78.9348301333	View between House 6 (right) and House 7 (left). No feed bins or propane tanks. Area is vegetated with high grasses. Side vents are seen.
Photo 12	2011-06-17--09.54.20.JPG	N 39.1566477333 ,W -78.9344586	View between House 7 (right) and House 8 (left). Feed bins in foreground with propane tanks behind feed bins. Area is vegetated with high grasses.
Photo 13	2011-06-17--09.54.31.JPG	N 39.1566448 ,W -78.9344652	North end of House 8. Exterior of House 8 similar to House 1 (see photo 5). Access lane wraps around to east side of House 8.
Photo 14	2011-06-17--09.54.58.JPG	N 39.1565768 ,W -78.9342966	From the north end of House 8, view of the east side of House 8. Gravel access lane travels parallel to House 8. Side vents and exhaust fans for the tunnel ventilation system are seen. PVC pipes low on the house are for rodent control. Manure shed and compost shed on left.
Photo 15	2011-06-17--09.55.26.JPG	N 39.1565624667 ,W -78.9342700667	From north end of House 8, view of north end of all eight houses. Gravel access lane extends to entrance at far end.
Photo 16	2011-06-17--09.58.38.JPG	N 39.1558903333 ,W -78.9345652667	View of north end of Manure Shed. Manure Shed open on north end with low side walls. Manure shed is roofed and is without siding on all sides. The floor of the Manure Shed is concrete and extends outside. Stormwater ponding was observed near entrance inside the manure shed. Bedding is seen in southwest corner of the shed.

Photo Reference	Photo Filename ¹	Coordinates Where Photo Taken	Description
Photo 17	2011-06-17--10.00.14.JPG	N 39.1559436667 ,W - 78.934504	Concrete pad of manure shed extends the length of the compost shed. Compost shed sloped to drain water behind structure (east side).
Photo 18	2011-06-17--10.00.33.JPG	N 39.1558796667 ,W - 78.9344508	Wet area on the northwest corner of the concrete pad shows the drainage pattern flows into the vegetated area to the north of the gravel access lane.
Photo 19	2011-06-17--10.00.53.JPG	N 39.1558472667 ,W - 78.9344801333	Wet area on west side of the concrete in front of the access lane shows water drains to the south side of the gravel access lane.
Photo 20	2011-06-17--10.01.43.JPG	N 39.1559248 ,W -78.9345778	View of the vegetated area to the north of the compost/manure shed concrete pad.
Photo 21	2011-06-17--10.01.50.JPG	N 39.155939 ,W - 78.9346165333	View of the vegetated area between the manure shed and the access lane along House 8.
Photo 22	2011-06-17--10.04.51.JPG	N 39.1555174667 ,W - 78.9352164	From south end of House 8, view of south end of all eight houses. Gravel access lane extends to House 1 at far end. Gravel is different from the gravel along the north end and east side of House 8.
Photo 23	2011-06-17--10.05.00.JPG	N 39.1555240667 ,W - 78.9352002	South end of House 8. House 8 has sliding door with black, hard pack gravel (approx. 15') and extends from house (approx. 4') in front of doors.
Photo 24	2011-06-17--10.05.17.JPG	N 39.1555564667 ,W - 78.9351964667	Manure is observed on edge of grass line.
Photo 25	2011-06-17--10.05.21.JPG	N 39.1555611333 ,W - 78.9351984667	Manure is observed on edge of grass line.
Photo 26	2011-06-17--10.07.00.JPG	N 39.1555836667 ,W - 78.9354190667	Inlet to culvert (center) between Houses 7&8 that runs underneath access lane on the south end.
Photo 27	2011-06-17--10.08.15.JPG	N 39.1555914 ,W - 78.9353835333	Close up of culvert in Photo 26
Photo 28	2011-06-17--10.09.20.JPG	N 39.1557793333 ,W - 78.9355530667	Inlet to culvert (center) between Houses 6&7 that runs underneath access lane on the south end.
Photo 29	2011-06-17--10.09.43.JPG	N 39.1557948 ,W -78.9355552	Close up of culvert in Photo 28
Photo 30	2011-06-17--10.10.25.JPG	N 39.1557728 ,W -78.9355998	Corresponding outlet to the inlet, shown in Photos 28 & 29, between Houses 6&7.
Photo 31	2011-06-17--10.10.50.JPG	N 39.1557102 ,W - 78.9356467333	View of pasture beyond outlets with tree line demarking the approximate location of the stream.

Photo Reference	Photo Filename ¹	Coordinates Where Photo Taken	Description
Photo 32	2011-06-17--10.10.54.JPG	N 39.155707 , W - 78.9356456667	More easterly view of the pasture shown in Photo 31. Fence (foreground) at Alt property boundary.
Photo 33	2011-06-17--10.11.00.JPG	N 39.1557022 , W - 78.9356440667	More westerly view of the pasture shown in Photo 31. Fence (foreground) at Alt property boundary.
Photo 34	2011-06-17--10.12.42.JPG	N 39.1559406 , W -78.935939	General area of the inlet between Houses 5 & 6.
Photo 35	2011-06-17--10.38.10.JPG	N 39.156872 , W - 78.9375516667	View of Mudlick Run. Stream is approximately 10' below a steep embankment.
Photo 36	2011-06-17--10.38.18.JPG	N 39.1568432 , W - 78.9375271333	Slightly upstream view of Photo 35.
Photo 37	2011-06-17--10.38.31.JPG	N 39.1568352667 , W - 78.9375246667	Slightly downstream view of Photo 35.
Photo 38	2011-06-17--10.40.35.JPG	N 39.157157 , W -78.937082	Area devoid of grass shows flow pattern of roof runoff from west side of House 1 into a vegetated ditch.